

## Hardware Information

New customers can purchase hardware from Node1 Internet as part of ordering an internet service. All hardware will be pre-configured for your service. Existing customers can also purchase hardware by contacting us on 08 9964 5464, emailing [info@node1.com.au](mailto:info@node1.com.au) or visiting our store at 218B Lester Avenue, Geraldton WA 6530.

| Product Description   | Manufacturer | Technical Information   | Price | Warranty | Post-Sales Support  |
|---|--------------|---|-------|----------|---|
| <b>Mikrotik QRT-5 AC: High Performance Backbone wireless with 23dBi antenna</b> | Mikrotik     | For more information about the Mikrotik QRT visit <a href="http://www.mikrotik.com/">http://www.mikrotik.com/</a>   | \$300 | 1 year   | For support regarding this product please call 08 9964 5464 or visit us in store. If your antenna has become faulty outside of the warranty period a fee of \$300 for a new antenna, and an installation fee of \$55 applies.   |
| <b>Ubiquiti PowerBeam PBE-5AC-300</b>   | Ubiquiti     | For more information about the Ubiquiti PowerBeam PBE-5AC-300 visit <a href="https://www.ubnt.com/airmax/powerbeam-ac/">https://www.ubnt.com/airmax/powerbeam-ac/</a> | \$300 | 1 year   | For support regarding this product please call 08 9964 5464 or visit us in store. If your antenna has become faulty outside of the warranty period a fee of \$300 for a new antenna, and an installation fee of \$55 applies.   |
| <b>Ubiquiti PowerBeam PBE-5AC-400</b>   | Ubiquiti     | For more information about the Ubiquiti PowerBeam PBE-5AC-400 visit <a href="https://www.ubnt.com/airmax/powerbeam-ac/">https://www.ubnt.com/airmax/powerbeam-ac/</a> | \$300 | 1 year   | For support regarding this product please call 08 9964 5464 or visit us in store. If your antenna has become faulty outside of the warranty period a fee of \$300 for a new antenna, and an installation fee of \$55 applies.   |
| <b>Ubiquiti PowerBeam PBE-5AC-500 with ISO</b>                                  | Ubiquiti     | For more information about the Ubiquiti PowerBeam PBE-5AC-500 visit <a href="https://www.ubnt.com/airmax/powerbeam-ac/">https://www.ubnt.com/airmax/powerbeam-ac/</a> | \$300 | 1 year   | For support regarding this product please call 08 9964 5464 or visit us in store. If your antenna has become faulty outside of the warranty period a fee of \$300 for a new antenna, and an installation fee of \$55 applies.   |
| <b>Ubiquiti PowerBeam PBE-5AC-620 with Radome</b>                               | Ubiquiti     | For more information about the Ubiquiti PowerBeam PBE-5AC-620 visit <a href="https://www.ubnt.com/airmax/powerbeam-ac/">https://www.ubnt.com/airmax/powerbeam-ac/</a> | \$600 | 1 year   | For support regarding this product please call 08 9964 5464 or visit us in store. If your antenna has become faulty outside of the warranty period a fee of \$600 for a new antenna, and an installation fee of \$55 applies.   |
| <b>Ubiquiti Rocket Prism RP-5AC-Gen2</b>  | Ubiquiti     | For more information about the Ubiquiti Rocket Prism visit <a href="https://www.ubnt.com/airmax/rocket-prism-ac/">https://www.ubnt.com/airmax/rocket-prism-ac/</a>    | \$800 | 1 year   | For support regarding this product please call 08 9964 5464 or visit us in store. If your antenna has become faulty outside of the warranty period a fee of \$800 for a new antenna, and an installation fee of \$55 applies.   |
| <b>NetComm N300 WiFi Gigabit Router with VOIP – NF10WV</b>                      | NetComm      | For more information about the NetComm N300 Wifi Gigabit Router visit <a href="http://www.netcommwireless.com/">http://www.netcommwireless.com/</a>                   | \$149 | 1 year   | For support regarding this product please call 08 9964 5464 or visit us in store. If the router has been reset and you are unable to bring the router in to our store, or have it reconfigured over the phone, therefore require a technician to attend on site to reconfigure, a fee of \$55 will apply. |